




# NLA



MODEL	A	B MAX	C	D MAX	E MAX	XX=W+Y+Z	F	G	H	I
	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
NLA60/XX	600	1555	1020	2190	6050	< 5800	1500	460	910	500

